

Message Text

UNCLASSIFIED

PAGE 01 HONG K 11002 150941Z
ACTION SY-05

INFO OCT-01 EA-12 ISO-00 /018 W
-----096352 151310Z /40
R 150649Z AUG 78
FM AMCONSUL HONG KONG
TO SECSTATE WASHDC 2517

UNCLAS HONG KONG 11002

DEPT FOR A/SY/OPS/T FROM RSO MARSDEN

E.O. 11652: N/A
TAGS: ASEC
SUBJECT: LOCKS

POST IS CONSIDERING INSTALLATION OF BRINKS MOD 2020 LOCKS FOR ALL DOORS LEADING FROM LOBBY TO INTERIOR OF CONSULATE AS PART OF MINIMUM STANDARDS RENOVATIONS. AS DESCRIBED IN OPS/T MEMO 2/17/78, IT WOULD APPEAR THAT MSG IN BOOTH WOULD HAVE TO UNLOCK ALL SUCH DOORS FOR EACH AUTHORIZED VISITOR. DUE TO HIGH VOLUME, THIS SYSTEM COULD PROVE TO BE PROBLEM. A CYPHER LOCK WOULD APPEAR TO BE A SOLUTION BUT THE BASIC UGLINESS OF THE "BRUTE" MAKES IT WORTH AVOIDING. IS THERE ANY ATTRACTIVE LOOKING AND RELIABLE CYPHER TYPE CONTROL THAT CAN BE MATED TO THE 2020 USING A 24 VDC POWER SOURCE? POST INTENDS TO USE PRESSURE MATS ON THE FLOORS BEHIND SEVERAL OF THE DOORS TO PROVIDE EGRESS FROM CONTROLLED AREAS. WILL THIS CAUSE ANY PROBLEMS? LOCKS WILL HAVE MANUAL KEY OVERRIDES ON BOTH SIDES. IN AN EMERGENCY THE MSG WOULD CUT POWER TO THE LOCKS LEAVING THEM SECURED TO PREVENT BOTH ACCESS AND INADVERTANT OPENING FROM THE INSIDE. BASIC RENOVATION DESIGN HAS BEEN APPROVED BY PRINCIPAL OFFICER. POST IS AWAITING FINAL DESIGN PLANS, ARTIST CONCEPTIONS, AND DECISION ON EXACT TYPES OF MATERIALS TO BE USED. YOUR RESPONSE TO ABOVE QUESTIONS AND RESULTS OF TESTING OF GLASS SAMPLES ARE ANXIOUSLY AWAITED SO THAT PLANS CAN BE FINALIZED AND FORWARDED TO DEPT FOR APPROVAL AND FUNDING. ASSISTANCE OF OPS/T IS GREATLY APPRECIATED.

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 HONG K 11002 150941Z

SHOESMITH

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 15 aug 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978HONGK11002
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780333-0689
Format: TEL
From: HONG KONG
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780864/aaaacbfq.tel
Line Count: 56
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 4c0b8663-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 08 jun 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1739678
Secure: OPEN
Status: NATIVE
Subject: LOCKS POST IS CONSIDERING INSTALLATION OF BRINKS MOD 2020 LOCKS FOR ALL DOORS LEADING FROM LOBBY TO INTERIOR OF CONSUL
TAGS: ASEC
To: STATE
Type: TE
vdkgvkey: odbc://SAS/SAS.dbo.SAS_Docs/4c0b8663-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014